



सत्यमेव जयते


INDIA NON JUDICIAL

Government of Punjab

₹50

e-Stamp

Certificate No. : IN-PB85912556792709V
 Certificate Issued Date : 31-Mar-2023 12:13 PM
 Certificate Issued By : pbnibahlu
 Account Reference : NEWIMPACC (SV)/ pb7004604/ HOSHIARPUR/ PB-HS
 Unique Doc. Reference : SUBIN-PBPB700460473129440874229V
 Purchased by : DHARAMVIR SHARMA SO RAM CHANDER RO MUKERIAN
 Description of Document : Article 4 Affidavit
 Property Description : Not Applicable
 Area of Property : Not Applicable
 Consideration Price (Rs.) : 0
 (Zero)
 First Party : DHARAMVIR SHARMA SO RAM CHANDER RO MUKERIAN
 Second Party : Not Applicable
 Stamp Duty Paid By : DHARAMVIR SHARMA SO RAM CHANDER RO MUKERIAN
 Stamp Duty Amount(Rs.) : 50
 (Fifty only)



Please write or type below this line



JD 0015976065

Statutory Alert:

1. The authenticity of this Stamp certificate should be verified at 'www.shcilestamp.com' or using e-Stamp Mobile App of Stock Holding. Any discrepancy in the details on this Certificate and as available on the website / Mobile App renders it invalid.
2. The onus of checking the legitimacy is on the users of the certificate.
3. In case of any discrepancy please inform the Competent Authority.

ਹਲਫੀਆ ਬਿਆਨ

ਮੈਂ ਧਰਮਵੀਰ ਸ਼ਰਮਾ ਪੁੱਤਰ ਸ੍ਰੀ ਰਾਮ ਚੰਦਰ ਵਾਸੀ ਮੁਕੇਰੀਆਂ, ਤਹਿਸੀਲ ਮੁਕੇਰੀਆਂ, ਜਿਲਾ ਹੁਸ਼ਿਆਰਪੁਰ, ਪੰਜਾਬ ਦਾ ਰਹਿਣ ਵਾਲਾ ਹਾਂ, ਟਰਾਂਸਪੋਰਟ ਦਾ ਹੇਠ ਲਿਖੇ ਅਨੁਸਾਰ ਪ੍ਰਬੰਧ ਹੈ ਤੇ ਬਿਆਨ ਕੀਤਾ ਜਾਂਦਾ ਹੈ ਕਿ-

1. ਸਕੂਲ ਬੱਸ ਬੱਚਿਆਂ ਨੂੰ ਲਿਆਉਣ ਅਤੇ ਲੈ ਕੇ ਜਾਣ ਲਈ ਬੱਸਾਂ ਦੀ ਗਿਣਤੀ 14 ਹੈ। ਜਿਹਨਾਂ ਦੇ ਰਜਿਸਟਰੇਸ਼ਨ ਨੰਬਰਾਂ ਦੀ ਲਿਸਟ ਨਾਲ ਨੱਥੀ ਹੈ ਜੀ।
2. ਉਪਰੋਕਤ ਬੱਸਾਂ ਹੋਰ ਟਰਾਂਸਪੋਰਟ ਦੇ ਸਾਧਨਾਂ ਕੋਲ ਫਿਟਨੈਸ ਸਰਟੀਫਿਕੇਟ ਅਤੇ ਇਹ ਸੜਕ ਤੇ ਚੱਲਣ ਯੋਗ ਹਨ।
3. ਉਪਰੋਕਤ ਬੱਸਾਂ ਜਾਂ ਹੋਰ ਟਰਾਂਸਪੋਰਟ ਸਾਧਨਾਂ ਕੋਲ ਪਰਮਿਟ ਹੈ।
4. ਉਪਰੋਕਤ ਗੱਡੀਆਂ ਦੇ ਨਾਲ ਕੰਡਕਟਰ ਵੀ ਹਨ।
5. ਗੱਡੀਆਂ ਦੇ ਡਰਾਈਵਰ ਵਰਦੀਆ ਪਹਿਨਦੇ ਹਨ।
6. ਗੱਡੀਆਂ ਦੇ ਡਰਾਈਵਰਾਂ ਕੋਲ ਵੈਲਿਡ ਲਾਇਸੈਂਸ ਹੈ।
7. ਗੱਡੀਆਂ ਦੇ ਡਰਾਈਵਰ ਕੋਲ 5 ਸਾਲ ਦਾ ਤਜਰਬਾ ਹੈ।
8. ਗੱਡੀਆਂ ਦੇ ਡਰਾਈਵਰ ਦਾ 3 ਵਾਰੀ ਤੋਂ ਜਿਆਦਾ ਚਲਾਣ ਨਹੀਂ ਹੋਇਆ।
9. ਬੱਸ ਦੇ ਉਪਰ ਸਕੂਲ ਦਾ ਨਾਂ ਬੋਰਡ, ਰੂਟ ਦਾ ਨਾਂ ਲਿਖਿਆ ਅਤੇ ਵਿੱਚ ਫਸਟੇਡ ਬਕਸੇ ਉਪਲਬੱਧ ਹੈ।
10. ਬੱਸ ਦੇ ਬੱਚਿਆਂ ਦੀ ਉਵਰਲੋਡਿੰਗ (ਡੇਢ ਗੁਣਾ ਤੋਂ ਜਿਆਦਾ ਨਹੀਂ ਹੈ)।
11. ਬੱਸ ਪਲੂਸ਼ਨ ਭਰੀ ਹੈ ਅਤੇ ਪਲੂਸ਼ਨ ਸਰਟੀਫਿਕੇਟ ਲਿਆ ਹੋਇਆ ਹੈ।
12. ਸਕੂਲ ਦੀਆਂ ਬੱਸਾਂ ਸਪੀਡ ਲਿਮਟ ਫੋਲੋ ਕਰਦੀਆਂ ਹਨ।
13. ਬੱਸਾਂ ਨੂੰ ਰੋਕਣ ਲਈ ਬੱਸ ਸਟਾਫ ਬਣਿਆ ਹੋਇਆ ਹੈ।
14. ਸਕੂਲ ਅੰਦਰ ਪਾਰਕਿੰਗ ਦੀ ਥਾਂ ਅਤੇ ਸਕੂਲ ਅੰਦਰ ਹੀ ਬੱਚਿਆਂ ਨੂੰ ਉਤਾਰਿਆ ਜਾਂਦਾ ਹੈ।
15. ਸਕੂਲ ਬੱਸ ਲਈ ਵਨ-ਵੇ ਟ੍ਰੈਫਿਕ ਹੈ।
16. ਸਕੂਲ ਅਧਿਕਾਰੀ ਸਕੂਲ ਵਿੱਚ ਆਉਣ ਵਾਲੇ ਟ੍ਰੈਫਿਕ ਨੂੰ ਕੰਟਰੋਲ ਕਰਦੇ ਹਨ।
17. ਸਕੂਲ ਬੱਸਾਂ ਦੇ ਡਰਾਈਵਰਾਂ ਅਤੇ ਕੰਡਕਟਰਾਂ ਲਈ ਰਿਫਰੈਸ਼ਰ ਕੋਰਸ ਕੀਤੇ ਜਾ ਰਹੇ ਹਨ।
18. ਟਰਾਂਸਪੋਰਟ ਸੇਵਾ ਸਰਟੀਫਿਕੇਟ ਐਮ. ਵੀ ਆਈ ਵਲੋਂ ਜਾਰੀ ਕੀਤਾ ਗਿਆ ਹੈ। ਜੋ ਨਾਲ ਨੱਥੀ ਹੈ।

For Woodbury World School

ਬਿਆਨ ਕਰਤਾ Manager



Balwinder Singh
SLOKarma & S.M.L
ਤਸਦੀਕ
ਚੌ. ਮ. ਮੁਕੇਰੀਆ
ਤਸਦੀਕ ਕੀਤਾ ਜਾਂਦਾ ਹੈ ਕਿ ਉਪਰੋਕਤ ਦਿੱਤੇ ਬਿਆਨ ਸਹੀ ਵਾ ਦਰੁਸਤ ਹੈ ਇਸ ਵਿੱਚ ਗਲਤ ਬਿਆਨੀ
ਨਹੀਂ ਕੀਤੀ ਗਈ ਅਤੇ ਨਾਂ ਹੀ ਛੁਪਾਈ ਹੈ।

ਅ. ਮ. 3829 88249656
ਮਿਤੀ-

AFFIDAVIT ATTESTED

For Woodbury World School

SATPAL NILOKIA
NOTARY PUBLICMukerian, Distt. Hoshiarpur (Pb)
Mobile No. 94648-39555

Regd. No. 11538 Exp. Dt. 12.10.24

ਬਿਆਨ ਕਰਤਾ Manager

05 APR 2023

LIST OF SCHOOL BUSES OF WOODBURY WORLD SCHOOL,VILLAGE-GALHRIAN
(MUKERIAN HAJIPUR ROAD)

S.No	Veh No	vehicle Regn No/Maker name/ mfg date
1	W. No 1	PB-07AL 5512 (TATA) 05/2013
2	W. No 2	PB-07AL 7607 (TATA) 05/2013
3	W. No 3	PB-07AL 7608 (TATA) 05/2013
4	B. No 4	PB-07AL 5510 (TATA) (07/2013)
5	W. No 5	PB07AS 0695 (TATA) 04/2014
6	B. No.6	PB07AS 2866(SML) 06/2014
7	B. No.7	PB07AS 2865 (SML) 01/2015
8	B. No-8	PB-07AS 38 31 (SML) 03/2015
9	B. No-9	PB-07AS 38 51 (SML) 03/2015
10	B. No-10	PB-07AS 9627(SML) 04/2016
11	B. No-11	PB-07BG 1267(SML) 01/2016
12	B. No-12	PB-07 BP 9415(SML) 12/2017
13	B. No-14	PB-07BP 9431 (SML) 01/2018
14	B. No-15	PB-07BP 9952 (SML) 01/2018


Woodbury World School


Principal

For Woodbury World School



Manager

www.woodburyworldschool.org


Mob No- 73411 00933

LIST OF SCHOOL BUSES OF WOODBURY WORLD SCHOOL, VILLAGE-GALHRIAN
(MUKERIAN HAJIPUR ROAD)

S.No	Veh No	vehicle Regn No/Maker name/ mfg date
1	W. No 1	PB-07AL 5512 (TATA) 05/2013
2	W. No 2	PB-07AL 7607 (TATA) 05/2013
3	W. No 3	PB-07AL 7608 (TATA) 05/2013
4	B. No 4	PB-07AL 5510 (TATA) (07/2013)
5	W. No 5	PB07AS 0695 (TATA) 04/2014
6	B. No.6	PB07AS 2866(SML) 06/2014
7	B. No.7	PB07AS 2865 (SML) 01/2015
8	B. No-8	PB-07AS 38 31 (SML) 03/2015
9	B. No-9	PB-07AS 38 51 (SML) 03/2015
10	B. No-10	PB-07AS 9627(SML) 04/2016
11	B. No-11	PB-07BG 1267(SML) 01/2016
12	B. No-12	PB-07 BP 9415(SML) 12/2017
13	B. No-14	PB-07BP 9431 (SML) 01/2018
14	B. No-15	PB-07BP 9952 (SML) 01/2018

Woodbury World School
Principal**For Woodbury World School**
Managerwww.woodburyworldschool.org
73411 00933

**SAFE VAHAN SCHEME
INSPECTION REPORT PERFORMA**

S.NO	PARTICULARS	INSPECTING REPORT
1.	School bus number	14 Nos.
2.	Permit fitness certificate (as per act 083) requirement first aid doc fire extinguisher.	Yes
3.	Stop sign arm towards co-driver side with stop sign (should project out when passenger door is open).	Yes
4.	Speed governor temper proof conveying with the requirements of rule 11 of mv (a) 1989.	Yes
5.	Retracting entry step vehicle should be incapable of motion without folding this step.	Yes
6.	School Bus insignia /color/150 mm golden Brown Band "SCHOOL BUS" must be written on the back and front of the bus. With name and telephone no. of the school (if it is hired bus "ON SCHOOL DUTY" should be written.	Yes
7.	Passenger door with reliable Lock /Emergency doors. Bus should be incapable of motion if any of the door is open and with indication of the same to the Bus driver when passenger door is open the hazard warning lights should operate automatically and stop signal arm should project out the co-driver side.	Yes
8.	Storage racks beneath seats except driver to Driver and last row seats.	Yes
9.	Seats facing passengers step well be provided with the partition preventing child from falling into the step well.	Yes
10.	Window of the bus be fitted with horizontal grills.	Yes
11.	Drivers should have 5 years' experience of Driving.	Yes
12.	Heavy Vehicles and has not been challenged more than twice in a year for the Red light jumping Drink driving etc. drivers conductor with first aid and fire Extinguisher techniques refresher course twice a year. Driver medically fit and should not suffering from any contagious disease. No smoking/drinking of alcohol/chewing of tobacco by Driver/Conductor.	Yes
13.	Compliance of other functions of school authority (a) Children should be trained to open the emergency doors of the Bus. (b) One day refresher course of first aid & fire extinguishing techniques should be conducted by School authority twice a day. (c) School authority should ensure formation of stretch of a road outside of the school. Prominently marked "SCHOOL ZONE" by introducing Traffic sign speed limit marking Zebra crossing, pelican signal to be operated during opening /closing timings to facilitate safe crossing of the children. (d) To ensure speed limit opposite School gate (10 kmph to 25 kmph). (e) To ensure boarding & alighting from the school Bus should be arranged on the school side of the road, So that children do not have to cross the road.	Yes

Woodbury World School

Signature of Principal

Mobile No. 98152-14252.

Signature of Transport Incharge

Mobile No. 7341150933

For Woodbury World School

Manager